


Automatic Box Labeling System with Scanner Verification

Overview: Taped boxes will exit the taping machine, evenly spaced. After two 90-deg turns, they will proceed onto the conveyor scale to be weighed. The box weight will be sent to the downline printers. Two corner-wrap labels (containing weight and other customer information) will be applied to the box. A scanner will verify a readable label. Unreadable labels will be diverted for rework.



VANDE BERG
SCALES
www.vbssys.com • 712.722.1181